

**Virginia Western Community College - Stormwater Management Facilities**

Number	BMP Type	Location	Online Date (Installation)	Ownership	Maintenance	Most Recent Inspection	Est. Drained Acreage			Hydraulic Unit Code	Discharge Water Body	Discharge Water Impairment	TMDL	WLA
							Pervious	Impervious	Total					
1	Outfall #1	37°14'45, 79°58'8	6/30/2005	VWCC / City of Roanoke	Internal	6/14/2016	24.86	15.90	40.76	RU14	Roanoke River	Bacteria, Benthic	2006, 2006	<i>E. coli</i> : 1.73E+09 cfu/year; Sediment: 2 tons/year
2	Outfall #2	37°14'35, 79°58'19	6/30/2005	VWCC	Internal	6/14/2016	1.41	3.99	5.40	RU14	Roanoke River	Bacteria, Benthic	2006, 2006	<i>E. coli</i> : 1.73E+09 cfu/year; Sediment: 2 tons/year
3	Outfall #3	37°14'51, 79°58'1	6/30/2005	VWCC	Internal	6/14/2016	1.50	1.09	2.59	RU14	Roanoke River	Bacteria, Benthic	2006, 2006	<i>E. coli</i> : 1.73E+09 cfu/year; Sediment: 2 tons/year
4	Outfall #4	37°14'48, 79°58'41	6/30/2005	VWCC	Internal	6/14/2016	8.01	4.12	12.13	RU14	Roanoke River	Bacteria, Benthic	2006, 2006	<i>E. coli</i> : 1.73E+09 cfu/year; Sediment: 2 tons/year
5	Outfall #5	37°14'52, 79°58'35	6/30/2005	VWCC	Internal	6/14/2016	5.38	3.74	9.12	RU14	Roanoke River	Bacteria, Benthic	2006, 2006	<i>E. coli</i> : 1.73E+09 cfu/year; Sediment: 2 tons/year
6	Basin	South Campus at the railroad tracks	6/30/2005	VWCC	Internal	6/30/2016	24.86	15.90	40.76	RU14	Roanoke River	Bacteria, Benthic	2006, 2006	<i>E. coli</i> : 1.73E+09 cfu/year; Sediment: 2 tons/year
7	Basin	North Campus at Lot 14	4/20/2011	VWCC	Internal	6/30/2016	8.01	4.12	12.13	RU14	Roanoke River	Bacteria, Benthic	2006, 2006	<i>E. coli</i> : 1.73E+09 cfu/year; Sediment: 2 tons/year
8	Basin	South Campus behind College Services Building	6/30/2005	VWCC	Internal	6/30/2016	1.50	1.09	2.59	RU14	Roanoke River	Bacteria, Benthic	2006, 2006	<i>E. coli</i> : 1.73E+09 cfu/year; Sediment: 2 tons/year
9	UGDS	Lot 15	7/20/2014	VWCC	Internal	6/30/2016	24.86	15.90	40.76	RU14	Roanoke River	Bacteria, Benthic	2006, 2006	<i>E. coli</i> : 1.73E+09 cfu/year; Sediment: 2 tons/year
10	Egg Crate Detention System	Frailin Center on Colonial Ave side	4/25/2013	VWCC	Internal	6/30/2016	24.86	15.90	40.76	RU14	Roanoke River	Bacteria, Benthic	2006, 2006	<i>E. coli</i> : 1.73E+09 cfu/year; Sediment: 2 tons/year
11	Egg Crate Detention System	Frailin Center on Colonial Ave side	4/25/2013	VWCC	Internal	6/30/2016	24.86	15.90	40.76	RU14	Roanoke River	Bacteria, Benthic	2006, 2006	<i>E. coli</i> : 1.73E+09 cfu/year; Sediment: 2 tons/year
12	Bioretention Filterra Unit	Parking Lot # 2	11/24/2009	VWCC	Internal	6/30/2016	24.86	15.90	40.76	RU14	Roanoke River	Bacteria, Benthic	2006, 2006	<i>E. coli</i> : 1.73E+09 cfu/year; Sediment: 2 tons/year
13	Bioretention Filterra Unit	Parking Lot # 12	11/24/2009	VWCC	Internal	6/30/2016	1.50	1.09	2.59	RU14	Roanoke River	Bacteria, Benthic	2006, 2006	<i>E. coli</i> : 1.73E+09 cfu/year; Sediment: 2 tons/year
14	Rain Garden	At College Services Building	11/24/2009	VWCC	Internal	6/30/2016	1.50	1.09	2.59	RU14	Roanoke River	Bacteria, Benthic	2006, 2006	<i>E. coli</i> : 1.73E+09 cfu/year; Sediment: 2 tons/year
15	Rain Garden	South end of Lot 2	11/24/2009	VWCC	Internal	6/30/2016	24.86	15.90	40.76	RU14	Roanoke River	Bacteria, Benthic	2006, 2006	<i>E. coli</i> : 1.73E+09 cfu/year; Sediment: 2 tons/year
16	Rain Garden	Lot 14	4/20/2011	VWCC	Internal	6/30/2016	8.01	4.12	12.13	RU14	Roanoke River	Bacteria, Benthic	2006, 2006	<i>E. coli</i> : 1.73E+09 cfu/year; Sediment: 2 tons/year
17	Rain Garden	Frailin Center Plaza	4/25/2013	VWCC	Internal	6/30/2016	24.86	15.90	40.76	RU14	Roanoke River	Bacteria, Benthic	2006, 2006	<i>E. coli</i> : 1.73E+09 cfu/year; Sediment: 2 tons/year